



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test Nov-1-07 Operator BP America Production Company API # 3004531331

Property Name NYE LINDA 001B-MV Location: Unit G Section 20 Township 30 Range 8
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing _____ Intermediate _____ Casing _____ Bradenhead _____

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Flowed	Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes							
10 minutes							
15 minutes							
20 minutes							
25 minutes							
30 minutes							
5 minute SI							

	Bradenhead	Intermediate
	Flowed	Flowed
Steady Flow		
Surges		
Down to Nothing		
No Flow		
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead _____ Intermediate _____

REMARKS:

1" on B.H.
1" on Inter could not find Inter.
have to dig more?

By Ray Indesma
Freek
(Position)

Witness _____