



OIL & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-12-07 Operator Black Hill API #30-0 39-2944b

Property Name Jic 30-3-33 Well No. 31 Location: Unit Section 33 Township 30N Range 3W

Well Status(Shut-In or Producing) Initial PSI: Tubing 50 Intermediate Casing 250 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
5 min	<u>0</u>		<u>250</u>		
10 min	<u>0</u>		<u>250</u>		
15 min	<u>0</u>		<u>250</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>✓</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Bradenhead needs to be plummed to surface.

By Chris Herlauf
Pumper
(Position)

Witness

E-mail address Cherhauf@bhep.com

