



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-11-07 Operator Black Hills API #30-0 39 29530
Property Name 116292-30 Well No. 34 Location: Unit 1 Section 30 Township 29N Range 2W
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate Casing 250 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>250</u>		
10 min	<u>0</u>		<u>250</u>		
15 min	<u>0</u>		<u>250</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>RCVD NOV 2 '07</u>
Gas	<u>OIL CONS. DIV.</u>
Gas & Water	<u>DIST. 3</u>
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

This well has A plunger lift and on this test
was in shut in mode.

By Judson Valdez Witness
lease operator
(Position)

E-mail address jvaldez@BH&P.com