



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2/15/08 Operator: Elm Ridge Exploration CO LLC API #30-043- 20711

Property Name Jicarilla 393 Well No. B3 Location: Unit M Section 22 Township 23^N Range 4^W

Well Status (Shut-In or Producing) Tubing 53 Intermediate Casing 53 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes <u>0</u>			<u>53</u>	Steady Flow <u> </u>	
10 minutes <u>0</u>			<u>53</u>	Surges <u> </u>	
15 minutes <u>0</u>			<u>53</u>	Down to Nothing <u> </u>	
20 minutes <u> </u>				Nothing <u>Y</u>	
25 minutes <u> </u>				Gas <u> </u>	
30 minutes <u> </u>				Gas & Water <u> </u>	
				Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

Slime hole



By

Witness

Pumper
(Position)

Paul Durr

E-mail address