



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 07157  
Unit McBarr

AM 8:36

# SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	<input type="checkbox"/>
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	<input type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 28, 1956

Well No. 14 is located 990 ft. from N line and 920 ft. from E line of sec. 23  
Section 20 23 31 Range  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Anteo P.O. San Juan New Mexico  
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 924 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

3-12-56. Total Dept. 2237'.  
 Log by Johns 5 1/8", 15.50', 3-55 casing (2227') set at 2237' with 75 sections  
 regular cement, 75 sections cement, 14 gal.  
 Held 1000' for 30 minutes.  
 Top of cement by temperature survey at 1960'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Ran Mineral Gas Company  
 Address Box 987  
Paria, New Mexico  
 By [Signature]  
 Title Petroleum Engineer