

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office San Antonio  
Lease No. 21-280731  
Unit Cala

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	APR 28 1959
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 27, 19 59

Well No. 1 is located 1000 ft. from N line and 1100 ft. from E line of sec. 15


1000 (1/4 Sec. and Sec. No.) 1000 (Twp.) 1000 (Range) 1000 (Meridian)  
1000 (Field) 1000 (County or Subdivision) 1000 (State or Territory)

The elevation of the derrick floor above sea level is 5000 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth - 2070 - Run logs, Top of the Pictured Cliffs formation is at 1970. Set 6 1/2 in. (2000') or 1 1/2" production casing at 2031' with 75 ex. cement. Cased out to 2070'. Washed hole dry, tested for 2 hours with 2000' pressure. Pipe stay.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company AMERICAN OIL & GAS COMPANY

Address San Antonio, Texas

By ORIGINAL SIGNED BY JOE C. SALMON

Title JOE C. SALMON