



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-23-08 Operator Burlington API #30-0 45, 21789

Property Name Kirk Lake Com Well No. 1A Location: Unit I Section 36 Township 29 Range 9

Well Status (Shut-In or Producing) Initial PSI: Tubing 20 Intermediate N/A Casing 50 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
5 min			50		
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow ☒	
Surges ☐	
Down to Nothing ☐	
Nothing ☐	
Gas ☐	
Gas & Water ☐	
Water ☒	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☒ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

4 gallon of water in 5 minutes
to drop on casing.

By Russell Elliott
Lease Oper.
(Position)

Witness Monica Kuehling

E-mail address _____