## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**



ALIG 1 9 2008

	<u> </u>	000
Sundry Notices and Reports on Wells		
	Bureau or Larre mar	Office
	1 anningtons, lote	Lease Number
		Jicarilla CONT 101
1. Type of Well	6.	If Indian, All. or
Gas		Tribe Name
	<b>-</b>	Jicarilla
	7.	Unit Agreement Name
2. Name of Operator		
Burlington Resources Oil & Gas Company LP	0	
2 4 1 0 DI N 0 0	8.	Well Name & Number
3. Address & Phone No. of Operator		T''''- 101 OT
		Jicarilla 101 8J
DO D 4200 F NW 07400 (505) 220 0700	0	A PAY XX7 11 A7.
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
		20.020.22460
4. Location of Well, Footage, Sec., T, R, M		30-039-23469
Sec., TN, RW, NMPM	10.	Field and Pool
Doory 2 Aty at 11, A title Ata	10.	A ICIO MIIGIA VVI
Unit K (NESW) 1820' FSL & 1580' FWL, Sec. 12, T26N, R04W NMPM		Tapacito PC
· · · · · · · · · · · · · · · · · · ·		
	11.	County and State
		San Juan Co., NM
Notice of Intent  Recompletion  Subsequent Report  Plugging  Casing Repair  Final Abandonment  Abandonment  Abandonment  Change of Plans  New Construction  Non-Routine Fracturin  Casing Repair  Water Shut off  Conversion to Injection		RCVD AUG 21 '08
13. Describe Proposed or Completed Operations		OIL CONS. DIV.
		OIL AMAY MIA
		DIST. 3
Please see attached for PA detail.		
14. I haraby contify that the foregoing is true and second	<del></del>	
14. I hereby certify that the foregoing is true and correct.		
Signed Milly Manna Tracey N. Monroe Ti	tle Staff Regulatory Tec	chnician Date 8/10/09
Tracey N. Homoc	tic <u>Start Regulatory Tec</u>	Date 0/15/00
This space for Federal or State Office use)		
•		Date
CONDITION OF APPROVAL, if any:		
itle 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of		
the United States any talke, fictitious or fraudulent statements or representations as to any matter within its jurisdiction		
	ACCEPTE	) FOR TECORD
	it with the first it colors	

AUG 2 0 2008

FARIMAGION FIELD OFFICE SW

NMOCD <sub>P</sub>

\$

## Jicarilla 101 8J

## API # 30-039-23469

8/7/08 MIRU A Plus Well Service. ND WH. NU BOP. RU floor. PU 1 ¼" tbg. & tag existing CIBP @ 3780'. Load csg & circ clean w/25 ½ bbls. Attempt to PT csg – bad test. Pumped ½ bpm @ 400#. Plug 1 3780' – 3108'. Pumped 19 sx Class G Cement. LD tbg to TOC.

8/8/08 TIH & tag TOC plug @ 3158'. TOH. RU wireline w/2 7/8" gauge ring . RIH to 2012'. POOH. RU wireline w/1 11/16" Bi-wire. RIH & perf 2 holes @ 2010'. POOH. RU wireline w/2 7/8" cement retainer. RIH & set @ 1962'. POOH & RD wireline. PU stinger. TIH & sting in to cement retainer. Attempt to est. rate into squeeze holes. Press to 1000#. Bled to 800# in 1 min. & held. Sting out. Load csg & attempt to PT csg. Test failed. Pumped ½ bpm @ 400#. Approved by Bryce Hammond w/JAT to set 250' Plug on top of cement retainer. Plug 2 1962' – 1679'. Pumped 8 sx Class G Cement. LD tbg to TOC.

8/11/08 TIH & tag TOC plug 2 @ 1694'. TOH & LD all tbg. Load csg w & attempt to PT. Test failed. Pumped ½ bpm @ 400#. RU wireline w/1 1/16" bi-wire. RIH & shoot 2 squeeze holes @ 282'. POOH & RD wireline. Ext circ out BH valve @ 2 bpm @ 100#. Circ clean w/37 bbls. Plug 3 282' – surface. Pumped 125 sx Class G Cement. Circ good cement out of BH valve. WOC. Open Well. Csg & BH on vacuum. RU wireline w/ 1 11/16" skinker bar. RIH & tag TOC @ 810'. Plug went down hole. RD wireline. RU Pump to BH. Load csg w/1/2 bbl. PT to 300# - held. Talked to Bryce Hammond w/JAT & he approved pumping 44 sx Cement down Csg & WOC. Plug 3A 810' – surface w/44 sx Class G Cement. WOC.

8/12/08 Load csg & PT to 1000# - held. TIH & tag TOC plug @ 142'. Plug 3B 142' - surface. Pumped 11 sx Class G Cement. LD all Tbg. RD floor. ND BOP. DO WH. Cut off WH. Cmt in csg @ surface. Cmt in BH down 5'. Top off & set PA marker w/15 sx Class G Cement. RD rig & equipment. Cut off anchors.