



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-16-09 Operator Burlington Res API #30-0 45-23696
Property Name Tapp Well No. 2A Location: Unit Section 17 Township 28 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing 114 Intermediate 11A Casing 143 Bradenhead 19

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min			143		
10 min			143		
15 min			144		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	/	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR / FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 13

INTERMEDIATE 11A

REMARKS:

Flowing whole line - 1/2" steam -

By Russell Elliott
Senior MEO
(Position)

2 2 1/2" ga to trailer
Witness Monica Cullum

E-mail address

