



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-21-09 Operator Burlingtrades API #30-0

Property Name Fluence C Well No. 2 Location: Unit Section 20 Township 28 Range 8

Well Status (Shut-In or Producing) Initial PSI: Tubing 123 Intermediate 30 Casing 137 Bradenhead 13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Bradenhead Int	Csg	Int	Csg	
TIME						
5 min		30			141	
10 min		30			141	
15 min		30			141	
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS		
BRADENHEAD	INTERMEDIATE	
Steady Flow		
Surges	✓	
Down to Nothing		✓
Nothing		
Gas		DIST. 3
Gas & Water	✓	
Water		OIL CONS. DIV.

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 7

INTERMEDIATE 0

RCVD MAY 21 '09

REMARKS:

BH had a puff when opened - then flowed with surges at 43 seconds - flowed w/ surges whole 15 minutes - Intermediate blew for 1.5 min.

By Ma. J. J.

Witness Monica Kunkling

(Position)

E-mail address

Plunger dropped in 7.5 min into BHT