

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-25-09 Operator Dugan Production Corp. API # 30-045-28980
Property Name MORRISON Well No 1 Location: Unit H Section 13 Township 22N Range 09W
Well Status(Shut-In or Producing) Initial PSI: Tubing 42 Intermediate Casing 90 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 minutes	<u>8</u>		<u>90</u>			Steady Flow	
10 minutes	<u>8</u>		<u>90</u>			Surges	
15 minutes	<u>8</u>		<u>90</u>			Down to Nothing	
20 minutes						Nothing	<u>✓</u>
25 minutes						Gas	
30 minutes						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:


CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN

BRADENHEAD 8

INTERMEDIATE

REMARKS:

By  Switcher
(Position)

Witness

