

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-13-09 Operator Dugan Production Corp. API # 30-045-32425
Property Name MONTE CARLO COM Well No. 90S Location: Unit E Section 7 Township 30N Range 14W
Well Status(Shut-In or Producing) Initial PSI: Tubing 75 Intermediate Casing 14 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		14			
10 minutes	0		14			
15 minutes	0		14			
20 minutes	0		14			
25 minutes						
30 minutes						

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
0	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

No Pressure on bradenhead

By

Kammie Stufflebeam
Switcher
(Position)

Witness

