NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

													'		
Date of Test	05-21-1	_ Operator		Dugan	Production	on Corp.	Corp.		30-045	32					
Property Nam	ne BLAC	KROCK	FEDER	RAL B	_Well No_	1	Location:	Unit	L	Section	8	Township	26N	Range	11W
Well Status(Shut-In or Producing) Initial PSI:				Tubing	Tubing 75 Intermediate		ate		Casing	7	5	Bradent	nead	Ø	
	*							 -					·		
OPEN BRA	ADENHEA	AD AN	D INT	ERME	DIATE	ΓΟ ΑΤΜ(OSPHERE	יוסמו	/IDUAL	LY FOR	15 N	IINUTES	EACH		
		PRÉS	SURE												
Bradenhead Interm									FLOW	CHARACT	ERIS	TICS			
TIME	BH Int	Csg	Int	Csg	ר				BRADI	ENHEAD	-	INTERME	DIATE	-	
5 mintues	0	75				Steady Flo	w					-		_	
10 minutes	0	75				Surges								_	
15 minutes	e	75	1			Down to No	othing	·						_	
20 minutes						Nothing	•	No	thi	ng			4.	_	
25 minutes						Gas							<u> </u>	_	
30 minutes						Gas & Wat	ter								
				_		Water								_	
				_											
<u>If bräden</u>	head flo	<u>wed v</u>	vater	<u>che</u>	ck all o	f the de	scription	is tha	at appl	y below	<u>:</u>				
		CLEAF	₹		FRESH		SALTY		SULFU	IR	BLAC	κ	_		
									_			31 12 34 60 L	00117	70	
5 MINUTE SHUŤ-IN BRADÉNHEA					AD -	,Ø		INTER	MEDIATE	Ē		- /38°		-1374	5
REMARKS:												4 P	FCFI		3
<u> </u>						_						78 4	BUN 2		819
<u>···</u>		<u> </u>						······································				\\OIL	CONS. DI	- DICT a	202
	<u> </u>											-\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	CONS. DI	- - 510 % @	
					<u></u>							/02	C(29Z	37.4/E	
Ву	Jesus.	M .	lerb.	10 M	# 8	26		Witnes	:s						
<i>-</i> ,	<u> </u>	<i>y</i> ()		cher	4 - 1		_	***************************************						-	
			(Posit				_								