

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX. (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

RCVD JUL 7 '09

OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST

Date of Test 05/13/09

Operator

Thompson Eng
Kenny Bruce

API #

30-045-26614

Property Name Charley J#1

Location:

Unit M

Section 21

Township 27N

Range 13W

(Well Name and Number)

Well Status: Shut-in or Producing

Producing

Pressures:

Tubing 79

Intermediate na

Casing 79

Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Bradenhead PSIs

Intermediate

Bradenhead Intermediate

| Time | BH Blowdown | Casing Monitor | INT Monitor |
|-------------|----------------|-------------------|----------------|
| 5 minutes | 0 | 78 | na |
| 10 minutes | 0 | 78 | na |
| 15 minutes | 0 | 78 | na |
| 20 minutes | | | |
| 25 minutes | | | |
| 30 minutes | | | |
| 5 minute SI | 0 | | |

| Intermediate Blowdown | Casing Monitor |
|--------------------------|-------------------|
| na | |
| na | |
| na | |
| | |
| | |
| na | |

| | | |
|-----------------|-------------------------------------|--------------------------|
| Steady Flow | <input type="checkbox"/> | <input type="checkbox"/> |
| Surges | <input type="checkbox"/> | <input type="checkbox"/> |
| Down to Nothing | <input type="checkbox"/> | <input type="checkbox"/> |
| No Flow | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Gas | <input type="checkbox"/> | <input type="checkbox"/> |
| Gas and Water | <input type="checkbox"/> | <input type="checkbox"/> |
| Water | <input type="checkbox"/> | <input type="checkbox"/> |

If bradenhead flowed water, check all of the descriptions that apply below:

Clear ☐Fresh ☐Salty ☐Sulfur ☐Black ☐

5 Minute Shut-in

Bradenhead

0

Intermediate

na

REMARKS:

By:

Kenny Bruce operator

(Position)

Witness: