			_
ے: مصامل کی	L	E	
Sübmit	DV	CIIIdii	
	~,		1

Print Form

## NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

## OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST**

Kunging Horse				
Date of Test 05/7/09 Operator Kannay Basic API # 30-045-28047				
Property Name Sullivan #9 Location: Unit K Section 15 Township 26N Range 12W				
(Well Name and Number)				
Well Status: Shut-in or Producing Producing DIST. 3				
Pressures: Tubing 18 Intermediate na Casing 3 Bradenhead 0				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
Bradenhead PSIs Intermediate Bradenhead Intermedia	ata			
<u>Time</u> BH Casing INT Intermediate Casing Blowdown Monitor Monitor Blowdown Monitor	410			
5 minutes 0 3 na na Steady Flow				
5 minutes 0 3 na na Surges 0				
15 minutes 0 3 na na Down to Nothing				
20 minutes No Flow ⊠				
25 minutes Gas Gas				
30 minutes Gas and Water				
5 minute SI 0 Water				
If bradenhead flowed water, check all of the descriptions that apply below:				
Clear				
5 Minute Shut-in Bradenhead 0 Intermediate na				
REMARKS:				
By: Witness:				
Kenny Bruce operator				
(Position)				