## , Submit by Émail

Print Form

## NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST**

		-					
Date of Test 6-1	19-09	Operator	Coleman Oil & G	ias	АР	30-045-3	4332
Property Name	FEDERAL COAL 34 #043 (Well Name and Number)	Location	on: Unit	Section	Township 27N	Range 13W	
Well Status: Sh	ut-in or Producing Pro	ducing					
Pressures:	Tubing 11 Inter	mediate	Casing	11 e	Bradenhead 0		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH							
Bradenhead PSIs		ls	Intermediate		,	Bradenhead	Intermediate
<u>Time</u>	BH Casing Blowdown Monitor	INT Monitor	Intermediate Blowdown	Casing Monitor	·	5 tudom oud	mormodiaco
10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	0 11 0 0 11 0 0 11 0 0 0 0 0 0 0 0 0 0				Steady Flow Surges Down to Nothing No Flow Gas Gas and Water Water		
If bradenhead flowed water, check all of the descriptions that apply below:							
Clear 🗌	Fresh 🔲	Salt	у 🗆	Sulfur	☐ Black	PEC	EIVED SASS
5 Minute Sh	ut-in Bradenhead	0	Intermediate			011 COL	NS. DIV. DIST. 3
REMARKS:						021292gt	SESTE TO SE
By: Mike Veazey, Lease opperator			Witness:				
	(Position)				f	· · · · · · · · · · · · · · · · · · ·	J