



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/4/09 Operator Benson Martin Green API #30-045-05700
Property Name Foster Kiddle Well No. 4 Location: Unit C Section 25 Township 26N Range 8W
Well Status (Shut-In or Producing) Initial PSI: Tubing 77.6 Intermediate N/A Casing 91.1 Bradenhead 1.3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg	BRADENHEAD	INTERMEDIATE
TIME							
5 min	<u>Ø</u>	<u>N/A</u>	<u>91.1</u>	<u>N/A</u>	<u>N/A</u>	Steady Flow	
10 min						Surges	
15 min						Down to Nothing <u>1.3</u> ✓	
20 min						Nothing	
25 min						Gas ✓	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE _____ BRADENHEAD Ø INTERMEDIATE _____

REMARKS: Down to Ø within seconds.

By Jim Barnes

Witness _____

Lesse Operator
(Position)

E-mail address _____

