



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/4/09 Operator Benson Martin Lee API #30-0 45-13305
Property Name Foster Liddle Well No. 7 Location: Unit P Section 13 Township 25N Range 8W
Well Status (Shut-In or Producing) Initial PSI: Tubing 34.6 Intermediate NA Casing 38.2 Bradenhead 2.1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	<u>Ø</u>	<u>N/A</u>	<u>38.2</u>	<u>N/A</u>	<u>N/A</u>	
10 min						
15 min						
20 min						
25 min						
30 min						

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>✓</u>	
Nothing		
Gas	<u>✓</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE N/A

REMARKS:

Down to Ø within seconds

By Jim Barnes

Witness _____

Lease Operator
(Position)

E-mail address _____

