Submit by Email

Print Form

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST

				i			
Date of Test	4/22/09	Operator	<i>(ukui</i>		AF	30-645	- 283 55
Property Name Property Peak 1 H # 20 Location: Unit H Section 1 Township 27N Range 10W (Well Name and Number)							
Well Status: Shut-in or Producing Reducing							
Pressures: Tubing 8.5 Intermediate Casing 27 Bradenhead 2							
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH							
	Bradenhead PSIs		Intermediate			Bradenhead Intermediate	
Time	BH Casing Blowdown Monitor N	INT Monitor	Intermediate Blowdown	Casing Monitor		Diaueilleau II	itermediate
5 minutes 10 minutes 15 minutes 20 minutes 25 minutes 30 minutes	2 27 27 27 27 27 2 27 27 2 27 27 27 27 2				Steady Flow Surges Down to Nothing No Flow Gas Gas and Water Water		
If bradenhead flowed water, check all of the descriptions that apply below:							
Clear 🔲	Fresh	Salty		Sulfur	☐ Blac	N RECE	IVED 3
5 Minute Sh	nut-in Bradenhead	2 In	termediate		☐ Blac	OIL CONS. DIV	IVED 10111213
REMARKS:		-		***************************************		1920202618	अ रा भावायांका
By: /ea	se Operator				Witness:	1-01	
	(Position)						