

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office SANTA FE

Lease No. 077372

Unit _____

30 045 09402

RECEIVED
MAY 7 1954
U. S. GEOLOGICAL SURVEY
WASHINGTON, D. C.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

MAY 5, 1954

DANSBY #2

Well No. _____ is located 990 ft. from $\left\{ \begin{matrix} N \\ S \end{matrix} \right\}$ line and 990 ft. from $\left\{ \begin{matrix} E \\ W \end{matrix} \right\}$ line of sec. 19

NE-NE 30N 12W N.M.P.M.
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
FULCHER-KUTZ SAN JUAN NEW MEXICO
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5846 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

SHOT OFF $5\frac{1}{2}$ " CASING AT 1365' AND PULLED SAME. SET CEMENT PLUG FROM TD(2013') UP INTO CASING SHOE WITH TOP OF PLUG AT APPROX 1930'. (USED 10 SAX) SET CEMENT PLUG WITH 10 SAX CEMENT FROM 1350' TO 1270'. SET CEMENT PLUG WITH 10 SAX FROM 600' TO 520'. PLACED 5 SACK OF CEMENT AT 90' IN BOTTOM OF SURFACE CASING. PLACED 5 SAX OF CEMENT IN TOP OF SURFACE CASING, WITH 4' OF $5\frac{1}{2}$ " CASING STICKING UP ABOVE GROUND AS A MARKER.

PITS FILLED AND LEASE CLEANED UP.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company DON TRADERS INC.

Address 254 NORTH LAUREL AVE.

DES PLAINES, ILL.

By Frank C. Barnes
FRANK C. BARNES
Title GEOLOGIST.