

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API #30-039-29213

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company McElvain Oil & Gas Properties, Inc.	Contact Randy J. Elledge	
Address PO Box 5610 Farmington NM 87499	Telephone No. 505-320-4969	
Facility Name Elk Com 10 #1C	Facility Type Oil and Gas Well	
Surface Owner Federal	Mineral Owner Federal	Lease No. NMNM98694

LOCATION OF RELEASE

Unit Letter F	Section 10	Township 25N	Range 2W	Feet from the	North/South Line 1450'FNL	Feet from the	East/West Line 2475'FWL	County Rio Arriba
------------------	---------------	-----------------	-------------	---------------	------------------------------	---------------	----------------------------	----------------------

Latitude 36°24'57"W Longitude 107°02'15"W

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 45 bbls	Volume Recovered 40 bbls
Source of Release Produced Water Tank	Date and Hour of Occurrence 11-13-2008	Date and Hour of Discovery 11-13-2008 12:00 pm
Was Immediate Notice Given? x Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD- Brandon Powell	
By Whom? Randy J. Elledge	Date and Hour 11-13-2008 4:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes x No	If YES, Volume Impacting the Watercourse.	
RCVD DEC 18 '08		
If a Watercourse was Impacted, Describe Fully.*		
OIL CONS. DIV. DIST. 3		
Describe Cause of Problem and Remedial Action Taken.* Livestock kicked open the valve on the produced water tank. Valve handles were removed and a fence was built around tanks.		
Describe Area Affected and Cleanup Action Taken.* The liquid was contained in the firewall. The soil was a tight clay, therefore the liquid was contained and easily recovered with a vacuum truck. Brandon requested soil samples as soon as the soil was dry enough to sample. Snow has covered the location ever since the spill date. Envirotech will sample as soon as drying occurs.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
OIL CONSERVATION DIVISION		
Signature: 	Approved by District Supervisor:  For: Charlie Perrin	
Printed Name: Randy J. Elledge	Approval Date: 12-18-08 Expiration Date:	
Title: Production Foreman/Environmental Agent	Conditions of Approval:	
E-mail Address: Relledge@wapitiscv.com	Attached <input type="checkbox"/>	
Date: 12-16-2008	Phone: 505-320-4969	

* Attach Additional Sheets If Necessary

Incident # nRMD 0928141450