

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Kelsi Gurvitz	
Address	3401 E. 30th St., Farmington, NM 87402	Telephone No.	505-599-3403	
Facility Name	San Juan 32-8 Unit #15M	Facility Type	Gas Well	API # 300-45-33772
Surface Owner	Federal	Mineral Owner	Federal	Lease No. NMSF-079351

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	24	T31N	R08W	1915'	North	1960'	West	San Juan

Latitude **36.88475° N** Longitude **107.62949° W**

NATURE OF RELEASE

Type of Release – Produced Water	Volume of Release – 70 BBLS	Volume Recovered – 70 BBLS
Source of Release: Water Pit Tank Overflow	Date and Hour of Occurrence unknown	Date and Hour of Discovery 12/12/09 – 4:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell: NMOCD	RCVD DEC 21 '09
By Whom? Kelsi Gurvitz	Date and Hour – 12/14/09 4:00 p.m.	OIL CONS. DIV.
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	DIST. 3

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **On December 12, 2009, a water pit tank overflowed due to a separator malfunction which caused the dump valve to hang open. Upon discovery, the well was shut-in.**

Describe Area Affected and Cleanup Action Taken.* **All fluid was contained within the cribbing of the lined pit. Approximately 70 BBLS of fluid was recovered by a vacuum truck; therefore there is no impact to the environment.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kelsi Gurvitz</i>	OIL CONSERVATION DIVISION	
Printed Name: Kelsi Gurvitz	Approved by District Supervisor: <i>Bob Bell</i>	For: <i>CP</i>
Title: Environmental Consultant	Approval Date: <i>1-6-10</i>	Expiration Date:
E-mail Address: kelsi.m.gurvitz@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/17/09 Phone: 505-599-3403		

* Attach Additional Sheets If Necessary

NAND 1000733956