

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised June 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Ed Hasely
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 326-9700
Facility Name	SAN JUAN 30-6 UNIT 474	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
		Lease No	NMSF-080712-A

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	27	030N	006W	1230	North	1660	East	Rio Arriba

NATURE OF RELEASE

Type of Release	Fruitland Coal Produced Water	Volume of Release	25 BBLs.	Volume Recovered	1 BBLs.
Source of Release	Pit Tank	Date and Hour of Occurrence	5/2/2005 1:00:00 PM	Date and Hour of Discovery	5/2/2005 1:00:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Denny Foust		
By Whom?	Ed Hasely	Date and Hour	5/2/2005 1:15:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully.\*

NA

Describe Cause of Problem and Remedial Action Taken.\*

The dump valve on the separator plugged off causing the liquids to be carried over to the compressor, which dumped the water to the pit tank. The pit tank overflowed approximately 25 bbls of produced water. Some water ran off location down the access road in a tire rut.

Describe Area Affected and Cleanup Action Taken.\*

A vacuum truck was used to recover the free standing liquids. The impacted soils on location and on the access road were back dragged to mix and break up any crust that may form.

Note: A message was left w/ Mr. Mark Kelly (BLM) on 5/2/05 at 3:15 pm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	Denny Foust for Charlie Penn		
Title: Environmental Representative	Approval Date:	Expiration Date:	
E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com	Conditions of Approval:	Attached	
Date: 5/3/05	Phone: (505) 326-9841 or 9537	<input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

NDG-F 0512437238