

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

30 045 30812

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Lance Oil & Gas, Inc.	Contact	Jo Becksted
Address	P. O. Box 70, Kirtland, NM 87417	Telephone No.	(505) 598-5601 Ext. 58
Facility Name	Salty Dog #2 SWD	Facility Type	Water Injection Well

Surface Owner	Bureau of Land Management	Mineral Owner	Bureau of Land Management	Lease No.	NMSF-079968
---------------	---------------------------	---------------	---------------------------	-----------	-------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	5	29N	14W	1495'	South	1477'	East	San Juan County

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	200 bbls	Volume Recovered	100 bbls
Source of Release	Broken fitting inside pump building	Date and Hour of Occurrence	5/1/2005 about 1:00 PM	Date and Hour of Discovery	5/1/2005 about 2:30 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mark Kelly, BLM, Steve Hayden, NMOCD			
By Whom?	Jo Becksted	Date and Hour 5/2/2005 @ 10:00 a.m.			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A			

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\* Pump vibration caused the fitting to break, thereby releasing produced water. Shut down unit, replaced fitting, put a brace on the affected line in order to eliminate future vibration.

Describe Area Affected and Cleanup Action Taken.\*

Area immediately surrounding pump building, and to an area approximately 10 feet around the building.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Jo Becksted</i>	OIL CONSERVATION DIVISION	
Printed Name:	Jo Becksted	Approved by District Supervisor:	<i>Denise Reut for Charlie Penwin</i>
Title:	Compliance Administrator	Approval Date:	<i>May 6, 2005</i> Expiration Date:
E-mail Address:	jbeckste@westerngas.com	Conditions of Approval:	<i>Testing impacted soil to determine additional actions</i>
Date:	Phone: (505) 598-5601 Ext. 58	Attached	<input type="checkbox"/>

\* Attach Additional Sheets If Necessary

11 DG-F 0512329/94