District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Division Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action .											
30-045-31121						OPERATOR Solution   So					
Name of Company Lance Oil & Gas Company, Inc.						Contact Jo Becksted 45 97 57 by Elips					
Address P. O. Box 70, Kirtland, NM 87417						Telephone No. (505) 598-5601 Ext. 58					
Facility Name F-RPC 20 #3						Facility Type Gas Well					
Surface Ow	ner BL	M	Mineral C	wner	BLM			Lease N	lo. NMSF-079065		
Burrace Ow	ner BE			WIICI	DEMI LEGISTION THANKS 019003						
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/West Line		County	
M	20	29N	13W	660'		South	715,	West		San Juan County, NM	
								wcst		San Juan County, Nivi	
LatitudeLongitude											
NATURE OF RELEASE											
Type of Release Produced water							Volume of Release 3bbls Volume Recovered None				
Source of Release								Date and Hour of Discovery			
Stuffing Box on the Wellhead									Monday, 4/4/2005 @ 7:30 a.m.		
Was Immediate Notice Given?						If YES, To Whom?					
☐ Yes ☒ No ☐ Not Required											
D W						4/7/05, when Mark Kelly of the BLM informed her.					
By Whom? Mark Kelley, BLM							Date and Hour 4/7/2005 @ approx 12:00 noon				
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.					
							N/A				
If a Watercourse was Impacted, Describe Fully.*											
N/A											
Describe Cause of Problem and Remedial Action Taken.* Pumper discovered leaking stuffing box Monday morning on his run. He repaired the stuffing											
box, at which point the leaking ceased. Produced water remained in the soil immediately surrounding the wellhead until after Lance was informed of the											
spill on Thursday, 4/7/2005, at which point Lance collected a sample of the impacted soil, delivered it to iina' ba' for testing. The impacted soil was then											
scraped up and piled on to a liner on the well location, awaiting orders from the BLM to land farm.											
Describe Area Affected and Cleanup Action Taken.* The soil immediately surrounding the wellhead. It was scraped up and piled onto a liner on well											
location.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and											
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger											
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health											
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other											
federal, state, or local laws and/or regulations.											
OIL CONSERVATION DIVISION											
		$\mathcal{A}$									
Signature:		N/Vec			Denrygen						
		Ų.		Į.	Approved by District Supervisor:						
Printed Name	: Jo Be	cksted			tor charle I win						
Title:	Comp	liance Admin			Approval Date: 4/18 / 05 Expiration Date:						
Title: Compliance Administrator							<del>~ // 10 / °</del>	<u> </u>	Apiration	Date.	
E-mail Addre	ess: jbecks	te@westernga	is.com			Conditions of	Approval:			Amarica	
		<u> </u>			Attached						