

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-039-21275

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: CDX RIO, LLC	Contact: Lee Gardner
Address: 2700 Farmington Ave. Bldg K, Suite 1, Farmington NM 87401	Telephone No: (505) 326-3003
Facility Name: Jicarilla 147 #6	Facility Type: Oil & Gas Well
Surface Owner: Jicarilla Apache Tribe	Mineral Owner: Jicarilla Apache Tribe
Lease No: Jicarilla Contract 147	

LOCATION OF RELEASE

Unit Letter C	Section 6	Township 25N	Range 5W	Feet from the 790	North/South Line North	Feet from the 1850	East/West Line West	County Rio Arriba
------------------	--------------	-----------------	-------------	----------------------	---------------------------	-----------------------	------------------------	----------------------

Latitude 36.43411 Longitude 107.40379

NATURE OF RELEASE

Type of Release: Condensate, Oil & Water	Volume of Release: 100.7 barrels	Volume Recovered: 15 barrels
Source of Release: Production Tank	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 10:00 a.m. 11-30-07
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? Brandon Powell, OCD Herman Lujan, BLM Jicarilla Apache Tribal Environmental Protection Office	
By Whom? Lee Gardner	Date and Hour: 11:56 a.m. 11-30-07	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	

RCVD DEC 6 '07

OIL CONS. DIV.

DIST. 3

If a Watercourse was Impacted, Describe Fully.*
Not Applicable

Describe Cause of Problem and Remedial Action Taken.*
Drain valve on tank froze and broke. Drain valve was replaced

Describe Area Affected and Cleanup Action Taken.*

The material soaked into the ground around the production tank. The material migrated to the sump around the pit tank where some of it collected. 15 barrels of material were removed from the sump.

Action plan:
The facility was shutdown.
The production tank and pit tank and sump will be emptied and remove from their present location.
The production tank, pit tank and separator will be relocated on the well pad to a new lined dike area. All equipment will be above ground.
The contaminated dirt will be excavated and placed in a lined dike area until weather and road conditions allow for it to be safely hauled to a disposal site.
A third party environmental test firm will be contracted to sample the area to ensure all contamination has been removed.
Dirt from an approved site will be used to replace the contaminated dirt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Lee Gardner	Approved by District Supervisor: Brandon Powell	For: Charlie Perrin
Printed Name: Lee Gardner	Approval Date: 12-6-07	Expiration Date:
Title: HSE Coordinator	Conditions of Approval:	Attached ☐
E-mail Address: lee.gardner@cdxgas.com		
Date: December 5, 2007 Phone: 505-324-5427		

* Attach Additional Sheets If Necessary

n13P0800950061