

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Energen Resources	Contact: Kellie Skelton
Address: 2198 Bloomfield Hwy.	Telephone No.: 505-566-4682
Facility Name: State 29-10-2 #1	Facility Type: On shore gas/oil facility
Surface Owner: State	Mineral Owner: State
Lease No.: 30-045-28705	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	2	29N	10W	1125	North	1460	East	San Juan

Latitude 36.75833 Longitude -107.84953

NATURE OF RELEASE

Type of Release: Spill <i>crude oil</i>	Volume of Release: 90 bbls (est)	Volume Recovered: 70 bbls
Source of Release	Date and Hour of Occurrence: 12/12/2006 early am (estimated)	Date and Hour of Discovery: 12/12/2006 1:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Oil Conservation Division-Charlie Perrin	
By Whom? Kellie Skelton	Date and Hour: 12/13/2006 8:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* Bullet holes were shot into the tank side walls and let the fluid out of 2 different 30 caliber size holes. The fluid was caught in side the secondary containment. Sheriff's department was contacted, case #		
Describe Area Affected and Cleanup Action Taken.* A crew was called with a vacuum truck. The liquids were removed from secondary containment and placed into another tank. Soil was then removed and transported to Industrial Eco Systems for disposal. The tank was moved and soil removed under the tank. Soil removal was discontinued when hard rock was encountered.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Kellie Skelton</i>	OIL CONSERVATION DIVISION	
Printed Name: Kellie J. Skelton	Approved by District Supervisor: <i>Brandon Powell</i>	For: <i>Charlie Perrin</i>
Title: Environmental/Safety Coordinator	Approval Date: <i>12-12-06</i>	Expiration Date:
E-mail Address: <i>kskelton@energen.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/22/2006 Phone: 505-566-4682		

* Attach Additional Sheets If Necessary

nBP0701742576