

District I  
1625 N French Dr , Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company	Lance Oil & Gas, Inc.	Contact	Jo Becksted
Address	P. O. Box 70, Kirtland, NM 87417	Telephone No.	(505) 598-5601 Ext. 5558
Facility Name	Salty Dog #2	Facility Type	Salt Water Disposal Well
		API #	30-045-30812

Surface Owner	BLM	Mineral Owner	BLM	Lease No.	NMSF-079968
---------------	-----	---------------	-----	-----------	-------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	5	29N	14W	1495	South	1477	East	San Juan

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**



Type of Release	Produced Water	Volume of Release	8 bbls	Volume Recovered	7 bbls
Source of Release	Ruptured 3" Water Line	Date and Hour of Occurrence	7/25/06 @ 2:00 p.m.	Date and Hour of Discovery	7/25/06 @ 2:00 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?	Jo Becksted	Date and Hour	7/26/06 @ 2:45 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\* Roustabouts attempting to locate unmarked line, accidentally ruptured with a backhoe

Describe Area Affected and Cleanup Action Taken.\* The soil impacted is located in the pipeline right of way between the WF Federal 5 #2 and WF Federal 5 #3. The wells were immediately shut in until line was repaired, and the soil was spread out in the area to dry and to be recontoured and graded.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name:	Jo Becksted	Approved by District Supervisor:	 For: Charlie Perrin
Title:	Production Tech	Approval Date:	7/28/06
E-mail Address:	jbeckste@westernngas.com	Expiration Date:	
Date:	Phone: (505) 598-5601 Ext. 5558	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

~BP0622254710

