

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

APC 30-045-33906

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company XTO Energy Inc.	Contact Kim Champlin	RCVD MAY24'07
Address 2700 Farmington Ave, Bldg K, Ste. 1, Farmington, NM 87401	Telephone No. (505) 566-7954	OIL CONS. DIV.
Facility Name Jack Frost D #1F ✓	Facility Type Gas Well	DIST. 3

Surface Owner Federal	Mineral Owner	Lease No. NMSF077951
------------------------------	---------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	26	27N	10W	695	North	1270	West	San Juan

Latitude 36.55157 Longitude 107.86964

NATURE OF RELEASE

Type of Release Fresh Water	Volume of Release Approx 400 bbl	Volume Recovered Approx 200 bbl
Source of Release Frac Tank	Date and Hour of Occurrence 05/09/07, time unknown	Date and Hour of Discovery 05/09/07 time unknown
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell- OCD	
By Whom? Kim Champlin	Date and Hour 05/10/07 at approximately 3:45 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse. NA	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken * ☐ Location is a new drill location and being prepared for drilling operations. While contractor was hooking up to a frac tank a weld behind the valve on the frac tank broke and approximately 400 barrels of fresh water was lost on location. The tank was holding fresh water to be used during cementing.

Describe Area Affected and Cleanup Action Taken *

A vac truck was used to recover the water and approximately 200 barrels were recovered and put into the reserve pit while the frac tank was repaired.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kim Champlin</i>		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Kim Champlin		Approved by District Supervisor. <i>Brandon Powell</i> For: <i>Charlie Perrin</i>	
Title: Environmental Assistant		Approval Date 5-24-07	Expiration Date.
E-mail Address: Kim_Champlin@xtoenergy.com		Conditions of Approval:	
Date: 05/18/07 Phone: 505-566-7954		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary