



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-5-10 Operator Devon API #30-0 3922564
Property Name NEBU Well No. 44R Location: Unit _____ Section 17 Township 30N Range 7W
Well Status (Shut-In or Producing) Initial PSI: Tubing 20 Intermediate - Casing 58 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>0</u>		<u>58</u>	<u>-</u>	
10 min	<u>0</u>		<u>58</u>		
15 min	<u>0</u>		<u>58</u>		
20 min	<u>0</u>		<u>58</u>		
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>High Low Flow</u>	
Surges		
Down to Nothing	<u>30 sec.</u>	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

Slit Blow on Bradenhead

By

John A. [Signature]
Tester

(Position)

Witness

John [Signature]

E-mail address _____

