

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	5/30/10 Operator			Energen Resources				API#	3003927309		
Property Name		JICARILLA 98 12B (Well Name and Number)			Location: Unit P Section 18			ownship	26	Range .	3
Pressure (Shut-in or Producing) Tubing 145 Intermediate Casing 150 Bradenhead											
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH											
	Bradenhead				Interme	diate		Bradon	head	Intermed	lista
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor		termediate Howdown	Casing Monitor		Flow		Flowe	
5 minutes	0	150		-			Steady Flow				
10 minutes	0	160		-			Surges				
15 minutes	0	160	7	-			Down to Nothing				
20 minutes		100					No Flow				
25 minutes							Gas	X			
30 minutes							Gas and Water				
5 minute SI	0	160					Water	•			
If bradenhead flowed water, check all of the descriptions that apply below: Clear											
By Lea	u open	Hor			Wi	tness					

(Position)