



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District III3istrict.htm](http://emrdd.state.nm.us/ocd/District%20III3istrict.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-12-10 Operator Devon API #30-0 3929628
 Property Name ANERU Well No. 40914 Location: Unit _____ Section 10 Township 30^N Range 7^W
 Well Status(Shut-In or Producing) Initial PSI: Tubing 13 Intermediate 20 Casing 3 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	1	4	1	4
10 min	0	1	2	1	2
15 min	0	2	2	2	2
20 min	0	2	2	2	2
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		✓ 1 LB
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 1

REMARKS: Inter. Blew Down To 1 PSI. Steady Flow

By Juan P. Quintana
Tester
(Position)

Witness [Signature] - Devon

E-mail address _____

