



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-18-10 Operator Energen Resources API # 3003905797

Property Name JICARILLA 67 5 Location: Unit N Section 29 Township 25 Range 5  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 134 Intermediate        Casing 134 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>134</u>				Steady Flow	
10 minutes	<u>0</u>	<u>134</u>				Surges	
15 minutes	<u>0</u>	<u>134</u>				Down to Nothing	
20 minutes						No Flow	<u>X</u>
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	<u>0</u>	<u>134</u>				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear        Fresh        Salty        Sulfur       

5 Minute Shut-in Bradenhead 0 Intermediate       

REMARKS:

NOTHING ON BRADEN HEAD.

By S. A.

Witness       

LEASE OPERATOR

(Position)

