



**NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-21-10 Operator Energen Resources API # 3003960030

Property Name JICARILLA P 1 Location: Unit H Section 28 Township 24 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) _____ Tubing 78 Intermediate _____ Casing 127 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	<u>0</u>	<u>127</u>										
10 minutes	<u>0</u>	<u>127</u>										
15 minutes	<u>0</u>	<u>127</u>										
20 minutes												
25 minutes												
30 minutes												
5 minute SI	<u>0</u>	<u>127</u>										

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediat _____

REMARKS: NOTHING ON BRADENHEAD.



By [Signature]
LEASE OPERATOR
(Position)

Witness _____