



**NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 7/23/10 Operator Energen Resources API # 3003926607

Property Name SAN JUAN 30 4 UNIT 49 Location: Unit D Section 9 Township 30 Range 4  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 360 Intermediate N/A Casing 360 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Flow Description	Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor			
5 minutes	<u>No blow</u>	<u>360</u>	<u>N/A</u>	<u>N/A</u>		Steady Flow		
10 minutes	<u>No blow</u>	<u>360</u>	<u>N/A</u>	<u>N/A</u>		Surges		
15 minutes	<u>No blow</u>	<u>365</u>	<u>N/A</u>	<u>N/A</u>		Down to Nothing		
20 minutes						No Flow	<u>X</u>	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate N/A



REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By [Signature]  
Prager  
(Position)

Witness \_\_\_\_\_