



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-19-2010 Operator Energen Resources API # 3003905544

Property Name W O HUGHES 1 Location: Unit 1 Section 8 Township 24 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 85 Intermediate Casing 90 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>90</u>				Steady Flow	
10 minutes	<u>0</u>	<u>90</u>				Surges	
15 minutes	<u>0</u>	<u>90</u>				Down to Nothing	
20 minutes						No Flow	<u>X</u>
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	<u>0</u>	<u>90</u>				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

No pressure on bradenhead

By

[Signature]

Witness

Lease Operator

(Position)

