

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	5/10	5/19/2010 Operator			Energen Resources				.PI # 	3003906061		
Property Nam	ne	JICARIL	LA 123 C 5		Locatio	on: Unit N	Section	8 To	ownship	25	Range	4
		(Well Name	and Number)									
Pressure (Shut-in of Producing) Tubing				78	S Intermediate Casing			g <u>17</u>	S Bra	adenh	ead	0
OPEN	N BRADENH	EAD AND	INTERMEDIA	TE TO	ATMOSI	PHERE IND	IVIDUALL	for f	15 MINU	TES E	ACH	******
	E	Bradenhead			Interme			Braden	head	Interme	diate	
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor		ermediate lowdown	Casing Monitor			Flow		Flow	
5 minutes	0	175					Stea	dy Flow	p	 		
10 minutes	0	175						Surges				
15 minutes	0	175					Down to	•			<u></u>	*****
20 minutes							•	No Flow				·
25 minutes			W- 1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-		4 - 1-44 - 1-4		Gas and	Gas				
30 minutes							Gas an	Water				
5 minute SI	0	175						· · · · · ·				
If bradenhe	ead flowed v	vater, che	ck all of the d	escrip	tions tha	t apply belo	ow:					
Clear	F	resh _	Sal	ty .		Sulfur	-	_ Bla				
5 Minute SI	h ut-in B	radenhea	d <u>O</u>	Inter	mediat				293°	31-	123456	
REMARKS:									2627283	RECI	123456 EIVED 2010	
								,	13 OIT	CONS, I	OV. DIST 3	273/2
									1.657	*	C	30/
									.61	350 ⁵	1817181	<i>'</i>
n. i	Fuil r	2	S. A. C	2 L.	\A/:	4						
Ву	Leace	Das	Eith G	Wing.	<u>~</u> vvi	tness						
	Luse											
		(Position	1)					NI	MOCD Tes	t Area	С	567