

(Position)

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			(Jubo)		z copies to at	ove addie	33 j				
Date of Test	5/21	5 21 2010 Operator			r Energen Resources		ces A	API#	300	3906487	
Property Nam	JICARILLA F 16				Location: Unit G Section 15			ownship	26	Range 5	
		(Well Name	and Number)								
Pressure (Sh	ut-in of Prod	ducina	Tubing	L	, S Interme	diate	Casing 4	0 Br	adenh	ead O	
		31)				<u> </u>					_
OPEN	N BRADENH	EAD AND	INTERMEDIA	TE	TO ATMOSF	HERE IND	IVIDUALLY FOR	15 MINU	TES E	ACH	•••
				7 6		·	1				
	Bradenhead				Interme	diate		Braden	head	Intermedia	te
Time	BH Bl <i>o</i> wdown	Casing Monitor	Intermediate Monitor		Intermediate Blowdown	Casing Monitor	•	Flow		Flowed	
5 minutes	6	90					Steady Flow				
10 minutes	0	90		Ш			Surges				
15 minutes	0	90		П			Down to Nothing				
20 minutes		• •			· · · · · · · · · · · · · · · · · · ·	-	No Flow				
25 minutes				П			Gas				
30 minutes							Gas and Water				
5 minute SI	0	90			 		Water				
If bradenhe Clear 5 Minute S	F	vater, che resh _ radenhea	Sa	lty	criptions tha	t apply bel	<u>ow:</u> Bla	ack		_	
REMARKS:											
											_
					Salado					······	_
ву	Erik Petago Witness Leuse Operator										
-	Lease (perat	ov								-