



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/18/10 Operator Energen Resources API # 3003906535

Property Name JICARILLA 96 8 Location: Unit M Section 12 Township 26 Range 3

(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 67 Intermediate N/A Casing 96 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	96				Steady Flow	
10 minutes	0	96				Surges	
15 minutes	0	96				Down to Nothing	
20 minutes	0	96				No Flow	✓
25 minutes	0	96				Gas	
30 minutes	0	96				Gas and Water	
5 minute SI	0	96				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear    Fresh    Salty    Sulfur    Black   

5 Minute Shut-in Bradenhead 0 Intermediate   

REMARKS:

Braden head valve shut in May 14

By Ed. Edwards

Witness   

Lease operator

(Position)

