



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/19/10 Operator Energen Resources API # 3003906850

Property Name JICARILLA 95 7 Location: Unit A Section 36 Township 27 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Producing Tubing 120 Intermediate N/A Casing 161 Bradenhead 25

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	161				Steady Flow	
10 minutes	0	164				Surges	
15 minutes	0	164				Down to Nothing	✓
20 minutes	0	164				No Flow	
25 minutes	0	164				Gas	✓
30 minutes	0	164				Gas and Water	
5 minute SI	0	164				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead -0- Intermediate

REMARKS:

B.H valve shut-in May 14th

By Ed. Edwards Witness

Lease operator
(Position)

