



# NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/12/10 Operator Energex Resources API # 3003907728

Property Name SAN JUAN 30 4 UNIT 28 Location: Unit H Section 31 Township 30 Range 4  
(Well Name and Number)

Pressure (Shut-in) or Producing) Tubing 180 Intermediate N/A Casing 185 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>No blow</u>	<u>185</u>	<u>NA</u>	<u>N/A</u>		Steady Flow	
10 minutes	<u>No blow</u>	<u>190</u>	<u>NA</u>	<u>N/A</u>		Surges	
15 minutes	<u>No blow</u>	<u>195</u>	<u>NA</u>	<u>N/A</u>		Down to Nothing	
20 minutes						No Flow	<u>X</u>
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Don Dalt Witness \_\_\_\_\_  
Purgen  
(Position)

