



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

Date of Test 5/20/10 Operator Energen Resources API # 3003921243

Property Name JICARILLA 95 1A Location: Unit P Section 35 Township 27 Range 3  
(Well Name and Number)

Pressure (Shut-in or Producing) Producing Tubing 55 Intermediate N/A Casing 85 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	85				Steady Flow		
10 minutes	0	85				Surges		
15 minutes	0	85				Down to Nothing		
20 minutes						No Flow	✓	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	0	85				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate \_\_\_\_\_

REMARKS:

B.h. valve shut-in May 14th

By

Ed. Edwards  
lease operator

(Position)

Witness \_\_\_\_\_

