



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/19/2010 Operator Energen Resources API # 3003923394

Property Name JICARILLA 107 8 Location: Unit B Section 33 Township 26 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 0 Intermediate Casing 26 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	0	26										
10 minutes	0	26										
15 minutes	0	26										
20 minutes												
25 minutes												
30 minutes												
5 minute SI	0	25										

	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing		
No Flow	✓	
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

By Erik Retago Erik Retago Witness
Lease Operator
(Position)

