



**NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 5/18/10 Operator Energen Resources API # 3003927437

Property Name JICARILLA 99 7C Location: Unit K Section 13 Township 26 Range 3  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 94 Intermediate N/A Casing 106 Bradenhead -0-

**OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH**

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	0	106										
10 minutes	0	106										
15 minutes	0	106						✓				
20 minutes												
25 minutes										✓		
30 minutes												
5 minute SI	0	106										


**If bradenhead flowed water, check all of the descriptions that apply below:**

Clear  Fresh  Salty  Sulfur  Black

5 Minute Shut-in Bradenhead  Intermediat

REMARKS:

*Braden head shut-in May 14<sup>th</sup>.*



By Ed. Edwards  
lease operator  
(Position)

Witness \_\_\_\_\_