

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			(oop.oo .o		,			
Date of Test	5-17	-10	Operator —	Energen Resources		ces A	.PI# 300	3003921504	
Property Name		FEDI	ERAL 1	Location: Unit A Section 31			ownship 24	Range 3	
		(Well Name	and Number)			<u> </u>			
Pressure (Shu	t-in or Pro	ducing)	Tubinģ 🔟	10 Interme	diate	Casing <u>/</u> 2	Bradenh	ead 🗻	
OPEN I	BRADENH	EAD AND	INTERMEDIA	TE TO ATMOSF	HERE IND	IVIDUALLY FOR	15 MINUTES E	ACH	
`	Bradenhead			Interme	diate		Bradenhead	Intermediate	
Time	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes	-0	120				Steady Flow			
10 minutes	0	120	·			Surges			
15 minutes	4	120				Down to Nothing			
20 minutes		.,,,-				No Flow			
25 minutes						Gas			
30 minutes		:				Gas and Water		-	
5 minute SI	6	120				Water			
If bradenhea Clear 5 Minute Shu REMARKS:	F	resh _ radenhea	Sali	escriptions tha	Sulfur	Bla	RECEIVED UIL CONS. DIV. I		
By Lut	her &	læice	z	Wi	tness				
164	36 D	PERA T	tor.						

(Position)