



**NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/8/2010 Operator Energen Resources API # 3003926906

Property Name SAN JUAN 32 5 UNIT 108S Location: Unit P Section 27 Township 32 Range 6
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 75 Intermediate NA Casing 75 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Flow Description	Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor			
5 minutes	0	75	NA	NA		Steady Flow		
10 minutes	0	75				Surges		
15 minutes	0	75				Down to Nothing		
20 minutes	0	75				No Flow	X	
25 minutes	0	75				Gas		
30 minutes	0	75				Gas and Water		
5 minute SI	0	75				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:



By Richard Fairbanks
Lease Operator
(Position)

Witness _____