



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/7/10 Operator Energen Resources API # 3003929631

Property Name BULLRIDGE 101S Location: Unit E Section 33 Township 32 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 70 Intermediate NA Casing 70 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	0	70	NA	NA			NA
10 minutes	0	70					
15 minutes	0	70					
20 minutes	0	70					
25 minutes	0	70					
30 minutes	0	70					
5 minute SI	0	70					
						Steady Flow	
						Surges	
						Down to Nothing	
						No Flow	X
						Gas	
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate NA

REMARKS:



By Richard Fairbanks Witness _____
Lease Operator
(Position)