NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-18-10 **Operator** Energen Resources **API #** 3004320212

Property Name CHACON JICARILLA D 6 **Location:** Unit I Section 21 Township 23 Range 3

(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 140 Intermediate _____ Casing 145 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor
5 minutes	0	145			
10 minutes	0	145			
15 minutes	0	145			
20 minutes					
25 minutes					
30 minutes					
5 minute SI	0	145			

	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing		
No Flow	✓	
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediat _____

RECEIVED JUN 2010 OIL CONS. DIV. DIST. 3

REMARKS:

By Luther Pierce **Witness** _____

LEASE OPERATOR

(Position)

NMOCD Test Area: C 778