



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-18-2010 Operator Energen Resources API # 3003921935

Property Name JICARILLA WEST 8A Location: Unit J Section 6 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 170 Intermediate Casing 200 Bradenhead 15TM

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	200				Steady Flow	
10 minutes	0	200				Surges	
15 minutes	0	200				Down to Nothing	✓
20 minutes						No Flow	
25 minutes						Gas	✓
30 minutes						Gas and Water	
5 minute SI	0	200				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

To small to measure pressure.

By Alex Hovary

Witness

Field Operator

(Position)

