



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-18-2010 Operator Energen Resources API # 3003926306

Property Name JICARILLA WEST 9M Location: Unit C Section 6 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 150 Intermediate Casing 160 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	160				Steady Flow		
10 minutes	0	160				Surges		
15 minutes	0	160				Down to Nothing		
20 minutes		16				No Flow	✓	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI	0	160				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

By Alex Hovey

Witness _____

Field Operator

(Position)

